



Adjustments of the motor currents

Tue Jan 2 11:19:41
2018

Adresse: <http://bechele.de/pages/english/139-0.html>
Autor: Rolf Jethon

The motor current adjustment pots on the stepper motor drivers are all set to the middle position from delivery. During operation I encountered from time to time knocking sounds from the extruder motors (especially on high printing speeds) and also I had a few lost steps of the delta tower motors.

So I increased the motor currents and had since then none of the reported problems any more.

See the image below:

