



Power supply via USB  
 Each potentiometer may consist out of a combination of two single Potentiometers  
 HID support via USB

Sheet: /  
 File: RPI\_zero\_RP2040.kicad\_sch

**Title: Joystick without dead zone - wiring**

Size: A4 Date: 22.02.2026

Rev: 1

KiCad E.D.A. 9.0.7

Id: 1/1